



**Step 1.** Prepare connector components and strip coaxial cable according to given dimensions (check point 1)




**Step 2.** Please slide ferrule onto cable and splay out cable braid




**Step 3.** Slide center contact up to dielectric and solder cable center conductor using minimum amount of solder paste through solder hole (check point 2)



**Step 4.** Push cable with center contact into connector main body until perceptible point. Cover cable braid over connector neck carefully



**Step 5.** Push ferrule toward main body and crimp ferrule with tool Hex size : .151"



**Assembly Method :**

Center contact : Soldered  
Outer contact : Crimp


**Crimp Tool PN :** 600600

**Crimp Head PN :** 60060060101




**Cable Type :** Flexible Cable RG316 Double Braid

**Cable Strip Dimensions (mm) :**



**Check Point :**

1. No components damaged and no cable braid split after stripping
2. No excess solder, melt dielectric, and misaligned center contact after assembling



3. Please double check connector interface or coaxial cable status if cable braid exposes. Simply remove or cut exposed cable braid with scissor or utility knife after check



4. No significant dog ear after crimping



Würth Elektronik eiSos GmbH & Co. KG  
EMC & Inductive Solutions

Max-Eyth-Str. 1  
74638 Waldenburg  
Germany  
com. +49 79 42 945 - 0

www.we-online.de  
eiSos@we-online.de



CREATED  
BMa

CHECKED  
JCh

DESCRIPTION

**Assembly instructions**

**616 460 211 106 20**

REVISION

STATUS

DATE

2020-03-02

BUSINESS UNIT

eiCan