Step 1. Create a panel cutout in the panel according to datasheet
It must be within 0.05 mm tolerance to ensure IP67 rating



(Example only)

Step 2. Install connector through the opening panel cutout from the inside
Be aware of maximum panel thickness recommended on datasheet



(Example: max. panel thickness 2.8 mm)

Step 3. Slide and twist the lock washer and hex nut onto connector body
Tighten the hex nut to 57 N-cm using torque wrench to ensure IP67 rating





WE Torque Wrench PN:
6006330101

IP67 Panel Protection
The gasket should be sandwiched tightly between the connector and panel



Note :

IP67 Test follows IEC-60529

IP**6**7 -> Totally protected against dust

IP6**7** -> Protected against liquid effects of temporary immersion between 15 ~ 100 cm (30 minutes)

Würth Elektronik eiSos GmbH & Co. KG
EMC & Inductive Solutions

Max-Eyth-Str. 1
74638 Waldenburg
Germany
com. +49 79 42 945 - 0

www.we-online.de
eiSos@we-online.de

WÜRTH ELEKTRONIK
MORE THAN YOU EXPECT

CREATED	CHECKED	
BMa	JCh	

DESCRIPTION
IP67 Rear Mount SMA Connector Installation Guide

REVISION	STATUS	DATE	BUSINESS UNIT
		2021-06-03	**eiCan**